

## SPECS

|                   |             |                  |                      |
|-------------------|-------------|------------------|----------------------|
| Ref No            | BK554555    | Location Country | United Kingdom       |
| Chassis #         | WV120023    | Ver/Class        | AUTOMATIC DIESEL     |
| Model Code        |             | Ext.Color        | Blue                 |
| Engine Size       | 2,000 cc    | Fuel             | Diesel               |
| Drive             | 4WD         | Seats            | 5                    |
| Transmission      | Automatic   | Doors            | 4                    |
| Mileage           | 71,200 mile | Weight           | 4,000 kg             |
| Engine Code       |             | Dimension        | 5.25 × 1.94 × 1.84 m |
| Steering          | Right       | M3               | 18.740               |
| Registration Year | 2015/08     |                  |                      |
| Manufacture Year  |             |                  |                      |

## STANDARD FEATURES

|                |   |                 |   |                   |   |              |   |
|----------------|---|-----------------|---|-------------------|---|--------------|---|
| CD Player      | ✓ | Sun Roof        |   | Leather Seat      | ✓ | Alloy Wheels | ✓ |
| Power Steering | ✓ | Power Window    | ✓ | A/C               | ✓ | ABS          | ✓ |
| Airbag         | ✓ | Radio           | ✓ | CD Changer        |   | DVD          |   |
| TV             |   | Power Seat      |   | Back Tire         |   | Grill Guard  |   |
| Rear Spoiler   |   | Central Locking |   | Jack              |   | Spare Tire   |   |
| Wheel Spanner  |   | Fog Lights      |   | Back Camera       |   | Push Start   |   |
| Keyless Entry  |   | ESC             |   | 360 Degree Camera |   |              |   |
|                |   |                 |   |                   |   |              |   |

## SUPPLIER'S CONDITION REPORT

|                   |         |     |      |
|-------------------|---------|-----|------|
| Corrosion         | NO      | YES |      |
| Under Body Holes  | NO      | YES |      |
| Under Body Broken | NO      | YES |      |
| Engine            | Working | NG  |      |
| Brake System      | Working | NG  |      |
| Heater            | Working | NG  |      |
| Power Window      | Working | NG  |      |
| Transmission      | Working | NG  |      |
| A/C               | Working | NG  |      |
| Audio System      | Working | NG  |      |
| 4WD               | Working | NG  | NONE |

## COMMENTS

THERE IS NO GUARANTEE ABOUT HOLES AND BROKEN

SOLD AS IS &amp; SHOWN

DATE 2021/11/24