

SPECS

| | | | |
|-------------------|-------------------|------------------|----------------------|
| Ref No | BK559269 | Location Country | Korea |
| Chassis # | KMHSW81UBFU330751 | Ver/Class | |
| Model Code | | Ext.Color | Pearl |
| Engine Size | 1,995 cc | Fuel | Diesel |
| Drive | 2WD | Seats | 5 |
| Transmission | Automatic | Doors | 4 |
| Mileage | 187,041 km | Weight | 1,820 kg |
| Engine Code | | Dimension | 4.70 × 1.88 × 1.68 m |
| Steering | Left | M3 | 14.844 |
| Registration Year | 2015 | | |
| Manufacture Year | | | |

STANDARD FEATURES

| | | | | | | | |
|----------------|---|-----------------|---|-------------------|---|--------------|---|
| CD Player | ✓ | Sun Roof | | Leather Seat | ✓ | Alloy Wheels | ✓ |
| Power Steering | ✓ | Power Window | ✓ | A/C | ✓ | ABS | ✓ |
| Airbag | ✓ | Radio | | CD Changer | | DVD | |
| TV | ✓ | Power Seat | ✓ | Back Tire | | Grill Guard | |
| Rear Spoiler | | Central Locking | ✓ | Jack | | Spare Tire | |
| Wheel Spanner | | Fog Lights | | Back Camera | ✓ | Push Start | ✓ |
| Keyless Entry | | ESC | | 360 Degree Camera | | | |
| | | | | | | | |

SUPPLIER'S CONDITION REPORT

| | | | |
|-------------------|---------|-----|------|
| Corrosion | NO | YES | |
| Under Body Holes | NO | YES | |
| Under Body Broken | NO | YES | |
| Engine | Working | NG | |
| Brake System | Working | NG | |
| Heater | Working | NG | |
| Power Window | Working | NG | |
| Transmission | Working | NG | |
| A/C | Working | NG | |
| Audio System | Working | NG | |
| 4WD | Working | NG | NONE |

COMMENTS

DATE 2021/12/10