




# Condition Check Report

Date H28.2.23

BF NO. <u>499374</u>	Chassis No. <u>ZAR93700003244896</u>	yard <u>ビズネツ</u>
----------------------	--------------------------------------	------------------

1 Coolant level	<input checked="" type="radio"/> OK	NG	*Added	8 Engine	<input checked="" type="radio"/> OK	NG	*Added additives
2 Oil level	<input checked="" type="radio"/> OK	NG	*Added	9 Transmission	<input checked="" type="radio"/> OK	NG	
3 Oil leaking	<input checked="" type="radio"/> OK	NG		10 Door mirror	<input checked="" type="radio"/> OK	NG	
4 Drive Shaft Boots	<input checked="" type="radio"/> OK	NG		11 Power window	<input checked="" type="radio"/> OK	NG	
5 Tire	<input checked="" type="radio"/> OK	NG		12 Air Condition <input type="checkbox"/> NO A/C	<input checked="" type="radio"/> OK	Wind blows	NG
6 Spare <input type="checkbox"/> Repaire Kit	<input checked="" type="radio"/> OK	NG		13 Warning lamp	<input checked="" type="radio"/> OK	NG	
7 Underneath Rust	<input checked="" type="radio"/> OK	NG		14 Sun Roof	<input type="radio"/> YES	NG	



15 Rear Camera	<input type="radio"/> YES	NG	
16 Power sliding door	<input type="radio"/> YES	NG	L · R
17 Radio Validation	<input checked="" type="radio"/> YES	NG	
18 CD Validation	<input checked="" type="radio"/> YES	NG	
19 DVD Validation	<input type="radio"/> YES	NG	

(Comment)

Ⓣ 215/45R17

For Export Inspection	<input type="radio"/> OK	<input checked="" type="radio"/> Fail(Small)	<input type="radio"/> Fail(Large)	<input type="radio"/> Border	Inspector <u>ノリヤ</u>	(チェック者忘れないこと)
-----------------------	--------------------------	--	-----------------------------------	------------------------------	----------------------	---------------

インスペクション基準はEAA検査  
 A(キズ) Y(ワレ) C(腐蝕) Pハゲ(ペイントハゲ)  
 U(へこみ) S(サビ) C穴(腐蝕穴) X=交換要(タイヤ、フロントガラス、ライト類)

